

Technical Note

Subject: Acoustic warning when closing the lid, while sample lift is in upper position.

13/10-2014/FIJQ

All TL/OSL readers produced after 1th. of January 2015, will be equipped with an acoustic alarm (Buzzer) which will sound if the lid down button is pressed while the sample lift is in the upper position.

This provides a warning for the user to confirm that the turntable (sample holder) has been placed correctly before continuing to lower the lid.
Placing the turntable incorrectly, will result in damage to the heating element.

This safety device can be installed as an upgrade on older controllers.